

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BR S	8	("4493975" "4659907" "5547393" "5590475" "D414364" "6061923" "0036995" "6189229" "20020043003").PN.	USPAT; EPO; JPO	2004/09 /09 14:39			0
2	BR S	1	re36995.pn.	USPAT; EPO; JPO	2004/09 /09			0
3	BR S	8	("3964708"   "4493975"   "4659907"   "4683369"   "4802287"   "4835879"   "4868998"   "4910385").PN.	USPAT	2004/09 /09 15:03			0
4	BR S	3	(34/96,97.ccls. 132/271.ccls.) and (support with cord)	USPAT; EPO; JPO	2004/09 /09 16:07			0
5	BR S	5	(34/96,97.ccls. 132/271.ccls.) and (hook with cord)	USPAT; EPO; JPO	2004/09 /09 16:06			0
6	BR S	7	(34/96,97.ccls. 132/27\$.ccls.) and (hook with cord)	USPAT; EPO; JPO	2004/09 /09 16:06			0
7	BR S	2	((34/96,97.ccls. 132/27\$.ccls.) and (hook with cord)) not ((34/96,97.ccls. 132/271.ccls.) and (hook with cord))	USPAT; EPO; JPO	2004/09 /09 16:06			0
8	BR S	6	(34/96,97.ccls. 132/27\$.ccls.) and (support with cord)	USPAT; EPO; JPO	2004/09 /09 16:08			0

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
9	BR S	3	((34/96,97.ccls. 132/27\$.ccls.) and (support with cord)) not ((34/96,97.ccls. 132/271.ccls.) and (support with cord))	USPAT; EPO; JPO	2004/09 /09 16:07			0
10	BR S	204	(34/96,97.ccls. 132/27\$.ccls.) and (cord)	USPAT; EPO; JPO	2004/09 /09 16:08			0
11	BR S	1	(34/96,97.ccls. 132/27\$.ccls.) and (cord with hang)	USPAT; EPO; JPO	2004/09 /09 16:08			0
12	BR S	2	(34/96,97.ccls. 132/27\$.ccls.) and (cord with hang\$3)	USPAT; EPO; JPO	2004/09 /09 16:08			0
13	BR S	1	((34/96,97.ccls. 132/27\$.ccls.) and (cord with hang\$3)) not ((34/96,97.ccls. 132/27\$.ccls.) and (cord with hang))	USPAT; EPO; JPO	2004/09 /09 16:12			0
14	BR S	31	(electric\$3 with cord) and (cord with hang\$3 with housing)	USPAT; EPO; JPO	2004/09 /09 16:16			0
15	BR S	574	(electric\$3 with cord) and (cord with hook)	USPAT; EPO; JPO	2004/09 /09 16:23			0
16	BR S	47	(electric\$3 with cord) and (cord with hook with hang\$3)	USPAT; EPO; JPO	2004/09 /10 13:31			0
17	BR S	3	("4673148"   "5026016"   "D343024").PN.	USPAT	2004/09 /09 16:38			0

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
18	BR S	32	("4193209" "38648 47" "5280679" "425 5871" "2734282" "2 184858" "2262274" " "3287824" "535141 7" "2389822" "0647 485" "5873467" "D 451247" "D456951" " "5084984" "D3027 44" "D299559" "47 54769" "D292625" " "D286211" "D2869 26" "D453858" "44 64906").PN. ("5568691" "55156 21" "5249367" "513 0551" "5459944" "6 405387").PN.	USPAT; EPO; JPO	2004/09 /10 13:55			0

	Document ID	Issue Date	Title	Current OR	Current XRef	Inventor
1	US 6762425 B1	2004 0713	Portable device for curing gel nail preparations	250/504 R	250/455.1 1; 250/492.1	Strait, Gloria
2	US 6490832 B1	2002 1210	Sliding door system	52/207	49/360	Fischbach, Stefan et al.
3	US 6408924 B1	2002 0625	Control system for a vertical vane covering for architectural openings	160/168.1V	160/173V; 160/177V	Anderson, Richard N. et al.
4	US 6325132 B1	2001 1204	Pantograph and control system for a vertical vane covering for architectural openings	160/173 V	160/178.1 V	Anderson, Richard N. et al.
5	US 6311756 B1	2001 1106	Mounting system for coverings for architectural openings	160/178.1V	160/902	Anderson, Richard N. et al.
6	US 6135188 A	2000 1024	Tassel for control system for a vertical vane covering for architectural openings	160/178.1V	160/900	Anderson, Richard N. et al.
7	US 6123434 A	2000 0926	Fluorescent angle light	362/260	362/220; 362/285; 362/287; 362/427	Meltzer, Edward
8	US 6116322 A	2000 0912	Control system for a vertical vane covering for architectural openings	1/1		Anderson, Richard N. et al.
9	US 6098326 A	2000 0808	Locator sign	40/575	40/564	Campbell, III, Warren A.
10	US 5641223 A	1997 0624	Horticulture lamp	362/122	362/407; 362/410; 362/805	Rustebakke, Susan K.
11	US 5617087 A	1997 0401	Parking aid for parking vehicles in a covered garage	340/932.2	116/29; 200/61.41;	Scott, Thomas J.
12	US 5572319 A	1996 1105	Stain detector apparatus and method	356/238.3	250/485.1	Blackman, Stephen E. et al.
13	US 5519782 A	1996 0521	Headphone	381/370	381/385	Shinohara, Ikuo et al.
14	US 5480315 A	1996 0102	Rigidly securable water resistive electrical connector	439/271	439/278; 439/587	Martinelli, Leonard A.

	Document ID	Issue Date	Title	Current OR	Current XRef	Inventor
15	US 5454056 A	1995 0926	Luminous pull-cord for electrical switch operation	385/16	362/556; 385/147; 385/25; 385/88; 385/901; 385/92	Brothers, Harlan J.
16	US 5413161 A	1995 0509	Solar powered window shade	160/7	160/168.1 P; 160/168.1 R; 160/178.1 R	Corazzini, Warren
17	US 5344333 A	1994 0906	Locking apparatus for electrical plug connector assemblies	439/320	439/106; 439/312	Haag, Philip E.
18	US 5327592 A	1994 0712	Stationary patient lift	5/81.1R	254/362; 5/89.1	Stump, Floyd V.
19	US 5186653 A	1993 0216	Smoke alarm remote disconnect	439/500	340/628; 439/507; 439/638	Robert, Normand A.
20	US 5142508 A	1992 0825	Aquatic transducer system	367/141	310/337; 340/566; 367/136; 367/93	Mitchell, Thomas R. et al.
21	US 5012457 A	1991 0430	Aquatic transducer system	367/175	340/566; 367/182; 381/165; 381/334	Mitchell, Thomas R. et al.
22	US 4888639 A	1989 1219	Endoscope apparatus having integrated disconnectable light transmitting and image signal transmitting cord	348/69	600/109; 600/132	Yabe, Hisao et al.
23	US 4825047 A	1989 0425	Temperature-responsive controller for waterbed mattress heaters	219/496	219/217; 219/419; 219/509; 236/57; 337/322; 5/422	Miles, Floyd D.
24	US 4551577 A	1985 1105	Retractable power center	174/57	174/48; 439/131	Byrne, Norman R.